



m-cramer Satellitenservices
Matthias Cramer
Holzhofallee 7
64295 Darmstadt
Tel: +49-(0)6151-2784 880
Fax: +49-(0)6151-2784 885
Mobil: +49-(0)163-286 4622

e-mail: info@m-cramer.de
www.m-cramer.de
www.m-cramer.shop

UID: DE262663625

RELEASE NOTES FOR 2.0.4.3

source: www.thuraya.com

date: 28.06.2022

THURAYA IP+

The latest available firmware for your Thuraya IP+ terminal is version 2.0.4.3. It was released in February 2022.

Version 2.0.4.3 provides the overall stability of the Thuraya IP+ terminals with support for new hardware versions for new terminals with Microchip Wi-Fi feature. This is a recommended upgrade that includes enhancements for both legacy and new terminals.

New Features/Enhancements:

- Microchip WLAN Support
This release provides Microchip WLAN auto-upgrade with new firmware version 2.1.4 and various fixes (see fixed SPR list below).

Fixes:

- Terminal reporting "No Power/blank LCD"
- Microchip WLAN firmware does not currently support SSID Broadcast Disable
- WLAN Log Enable button is on wrong support screen
- SSID change doesn't work with CM build 2.0.4.0
- Properties page shows WLAN local IP address as x.x.129.100
- WLAN clients drop during QoS changes
- Terminal Summary is displaying old-style X10/X20 Regional Status
- Removing "DHCP & Netmode settings" note under Settings page for units built with Microchip WLAN
- GPS stays active forever when pressed with Microchip WiFi on

Firmware compatibility:

IMEI No	MCN No	Firmware Version
3579320101xxxxxx	All except 3500709-0004	2.0.4.0
3579320101xxxxxx	3500709-0004	2.0.4.3
3579320103xxxxxx	All	2.0.4.3