FIRMWARE UPGRADE

THURAYA SATSLEEVE+

source: www.thuraya.com
date: 17.02.2022

Requirements for upgrade:

- Thuraya SatSleeve+

- SatSleeve+ / SatSleeve Hotspot upgrader programme (available on this page)

- USB data cable (included in your Thuraya SatSleeve+ / SatSleeve Hotspot packaging)

- PC with Windows 10, Windows 8/8.1, Windows 7 or Windows Vista

Before upgrading an Thuraya SatSleeve+, please check which firmware is installed (go to Menu > Security > S/W version). Perform the upgrade only if Thuraya releases a firmware version newer than your existing one.

Please follow the below steps:

Step 1

Download the below Thuraya SatSleeve+ Upgrader programme.

- **SatSleeve+ upgrader**

Run the setup file - the Upgrader program including the USB driver will be installed.

Step 2

Download the latest SatSleeve+ firmware release to your hard disk.

- **SatSleeve_Hotspot_v1. 0.3**

  Release notes:
  - GmPRS usage issue resolution for iphone
  - Registering Missed call in logs when iphone screen is locked

Step 3

Connect your SatSleeve+ with the PC/laptop via USB data cable.

You can now start the Upgrader programme and locate the firmware on your hard disk. The Upgrader programme will help you through the upgrade process.